

CORE LABORATORIES, INC.
 Petroleum Reservoir Engineering
 DALLAS, TEXAS

Page No. 1

CORE ANALYSIS RESULTS

#852

Company PRESTON OIL COMPANY
 Well B. G. S. GEARY NO. V-2031
 Field GRANNYS CREEK
 County CLAY State W. VA. Elev.

Formation BIG LIME-BIG INJUN FILE CP-1-6748
 Core Type DIAMOND Date Report 9-20-68
 Drilling Fluid SALT WATER Analyst BOYLE

Lithological Abbreviations

SAND - SD	DOLOMITE - DOL	MUDSTONE - MSH	SILTSTONE - STS	FINE - FINE	CRYSTALLINE - CLR	SHALLOWS - SHM	FRACSTED - FRAC	SLIGHTLY - SL
SHALE - SH	CHERT - CH	INTERCALATED - ICN	SANDY - SMT	MEEDIUM - MED	GRANITE - GRN	CLAY - CLY	LAMINATED - LAM	VERY - V
LIMESTONE - LIM	GYPSUM - GYP	INTERCALATED - ICN	LIMY - LMY	COARSE - COA	GRANULAR - GRN	VERMICULITE - VER	STYLOLITE - STY	WITH - W

SAMPLE NUMBER	DEPTH FEET	PERMEABILITY MPD DIA. 100°		POROSITY PER CENT	RESIDUAL SATURATION PER CENT PORE		SAMPLE DESCRIPTION AND REMARKS
		PERM. MAX.	PERM. MIN.		OIL	TOTAL WATER	
WHOLE CORE ANALYSIS							
1	1740-41	1.5	1.2	2.7	0.0	72.0	Lm, sl/sdy, frac
2	41-42	3.0*		2.4	0.0	64.4	Lm, sl/sdy, frac
	42-47						Not submitted
3	47-48	<0.1*		8.0	8.0	74.7	Lm, sl/shy, sl/sdy
4	48-49	<0.1	<0.1	6.4	1.0	79.6	Sd, lmy
5	49-50	0.1	0.1	7.7	3.1	75.4	Sd, lmy
6	50-51	0.6	0.5	9.1	4.1	64.4	Sd, sl/lmy
7	51-52	5.1	5.0	13.2	4.9	60.3	Sd, sl/lmy
8	52-53	23.0	22.0	14.8	6.3	59.7	Sd, sl/lmy
9	53-54	17.0	16.0	13.5	5.0	59.6	Sd, sl/lmy
10	54-55	4.8	4.6	12.4	6.3	52.7	Sd, sl/lmy
11	55-56	15.0	15.0	16.1	10.0	70.1	Sd, sl/lmy
12	56-57	1.7	1.7	14.0	8.8	55.2	Sd, sl/lmy
13	57-58	4.6	4.5	12.2	8.5	58.4	Sd, sl/lmy
14	58-59	0.3	0.3	6.1	6.7	53.3	Sd, sl/lmy
15	59-60	0.2	0.1	7.4	6.6	57.0	Sd, sl/lmy
16	60-61	0.2	0.2	7.7	8.8	48.9	Sd, sl/lmy
17	61-62	0.3	0.3	8.2	7.2	53.3	Sd, sl/lmy
18	62-63	0.6	0.6	5.8	4.2	54.1	Sd, sl/lmy
19	63-64	0.4*		5.3	4.8	56.0	Sd, sl/lmy
20	64-65	0.5	0.4	8.3	4.8	58.7	Sd, sl/lmy
21	65-66	0.4	0.4	13.1	13.8	63.6	Sd, sl/lmy
22	66-67	0.9	0.9	12.4	15.9	52.7	Sd, sl/lmy
23	67-68	0.2	0.2	12.4	16.1	59.7	Sd, sl/lmy
24	68-69	0.1	0.1	13.7	13.7	66.0	Sd, sl/lmy
25	69-70	1.3	0.7	8.9	10.4	63.4	Sd, sl/lmy
26	70-71	0.2	0.1	15.2	12.5	64.6	Sd, sl/lmy
27	71-72	1.1	1.1	15.3	18.3	58.9	Sd, sl/lmy
28	72-73	0.3	0.3	15.8	17.8	56.5	Sd, sl/lmy
29	73-74	0.1	0.1	13.6	11.5	73.2	Sd, sl/lmy
30	74-75	0.7	0.3	14.3	11.1	60.9	Sd
31	75-76	0.1*		15.2	10.1	56.5	Sd, very frac
32	76-77	0.3	0.2	15.3	11.2	55.6	Sd
33	77-78	0.1	0.1	15.2	9.1	56.9	Sd

These analyses, opinions or interpretations are based on observations and materials supplied by the client to whom, and for whose exclusive and confidential use, this report is made. The interpretations or opinions expressed represent the best judgment of Core Laboratories, Inc. (all errors and omissions excepted); but Core Laboratories, Inc. and its officers and employees, assume no responsibility and make no warranty or representations, as to the productivity, proper operations, or printability of any oil, gas or other mineral well or sand in connection with which such report is used or relied upon.

CORE LABORATORIES, INC.
 *Petroleum Reservoir Engineering
 DALLAS, TEXAS

File CP-1-6748 Page No. 2
 Well B. G. S. Geary No. V-2031

CORE ANALYSIS RESULTS

SAMPLE NUMBER	DEPTH FT FEET	PERMEABILITY MILLIDARCY MAX.	POROSITY PER CENT	INDIVIDUAL SATURATION PER CENT PORE		SAMPLE DESCRIPTION AND REMARKS
				OIL	TOTAL WATER	
34	1778-79	0.3	0.1	15.5	12.9	Sd
35	79-80	0.3	0.3	16.1	13.0	53.2 Sd
36	80-81	0.2	0.2	15.5	12.6	53.2 Sd, vert frac
37	81-82	0.1	0.1	15.6	15.8	55.4 Sd
38	82-83	0.2	0.1	15.4	10.6	58.5 Sd
39	83-84	0.2	0.1	15.6	15.5	52.5 Sd
40	84-85	0.4	0.3	16.3	17.6	51.4 Sd
41	85-86	0.5	0.3	15.8	13.0	53.7 Sd, sl/lmy
42	86-87	1.1	1.1	16.5	12.9	50.4 Sd, sl/lmy
43	87-88	1.6	1.5	17.8	13.1	48.2 Sd, sl/lmy
44	88-89	1.5	1.5	18.2	12.2	48.2 Sd, sl/lmy
45	89-90	1.9	1.8	18.5	10.2	49.8 Sd, sl/lmy
46	90-91	2.2	2.0	18.7	8.7	54.0 Sd
47	91-92	1.7	1.6	16.1	10.0	55.2 Sd
48	92-93	1.0	1.0	16.6	10.6	55.7 Sd
49	93-94	0.2	0.2	15.9	15.6	55.4 Sd
50	94-95	<0.1*	5.2	2.4	68.3	Sd, lmy, shy
51	95-96	<0.1*	6.8	6.9	76.9	lm, sdy, shy
52	96-97	0.2	0.1	10.8	0.6	86.1 Sd, lmy
53	97-98	0.1	0.1	12.8	1.7	86.3 Sd, lmy, silty
54	98-99	0.2	0.2	12.1	2.4	84.6 Sd, lmy, silty
55	99-00	0.1	<0.1	5.9	7.5	74.9 Sd, lmy, shy, silty
56	1800-01	0.1	0.1	8.6	1.4	73.2 Sd, lmy, shy, silty

*DENOTES PLUG PERMEABILITY